




LEAK TESTING MACHINES & WATCHMAKERS TOOLS

# PLAROX PR1 / PR3

### **Heating plate**

Plate for heating up watches prior to the condensation test.

Temperature adjustable by electronic regulator.







## Technical specifications

#### PLAROX PR1

Supply voltage:

Power:

Heating temperature\*:

Capapcity: Weight:

Dimensions (I/d/h):

90-260 V / 50-60 Hz 300 W

300 11

30 to 65°C

30 watches

4.5 Kg

290 x 330 x 68 mm

### PLAROX PR<sub>3</sub>

110-230 V / 50-60 Hz

900W

30 to 65°C

100 watches

22 Kg

900 x 350 x 110 mm

E: info@roxer.ch